## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.


Jos van den Bogerd et al.
ATTORNEY DOCKET NO. 143766
Serial No. 10/698,321

Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002




1/4

FIG. 1



2/3


FIG. 3




## MULTILAYERED ARTICLES AND METHOD OF MANUFACTURE THEREOF Jos van den Bogerd et al. ATTORNEY DOCKET NO. 143766 Serial No. 10/698,321 Cantor Colburn LLP, 55 Griffin Road South, Bloomfield, CT 06002

3/4

FIG. 4



LaB6 in Core Layer



LaB6 in Cap layer

4/4

